

RECEIVED

JAN 22 1993

DIVISION OF
OIL, GAS & MINING

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. GENERAL INFORMATION

1. Report Time Period: From (mo./yr.) 1-1-92 To (mo./yr.) 1-20-93
2. DOGM File Number: S / 053 / 027
3. Mine Name: Black Ridge No. 1
4. Mineral(s) Mined: Picture stone
5. Legal Description (Location of Lands Affected):
1/4, SW 1/4, Section 18, Township 42S, Range 14W
1/4, 1/4, Section , Township , Range
1/4, 1/4, Section , Township , Range
6. Name of Operator or Company: Joseph Cassetta dba Desert Landscapes
7. Permanent Address: 860 East 19th Street
Tucson, AZ 85719
(602) 623-1396

8. Company Representative (or designated operator):

Name: Joseph Cassetta

Title: Owner

Address: 860 East 19th Street, Tucson, AZ 85719

Phone: (602) 623-1396

☒ Please check if any of the above information has changed since previous year.

II. MINING AND RECLAMATION

1. Was the mine active during the past year? Yes ☒ No ☐

2. If active, how much ore or mineral was mined? Approximately 100 tons

3. How much new or additional acreage was affected during past year? no new acreage

4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

No new disturbances have occurred during the past year. Disturbances are contained within the same three (3) acres we have been working on for the past years. Using a track hoe, we mine boulders of picture stone to be cut in Tucson, AZ. Approximately 100 tons of stone have been removed.

5. How much acreage was reclaimed during past year? One (1) acre

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

Approximately one (1) acre was reclaimed by replacing excess material into places where picture stone was removed. We are awaiting BLM approval of the reclamation performed.

7. What is the total disturbed acreage at years end? Approximately three (3) acres
8. Briefly summarize mining and reclamation planned for the upcoming year.
We plan to continue removing picture stone, and continue reclaiming
where we have removed picture stone.
- _____
- _____

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. ADDITIONAL INFORMATION

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. SIGNATURE REQUIREMENT

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Joseph Cassetta

Title of Operator: Owner

Signature of Operator: 

Date: January 20, 1993

jb
MR-AR